

USE (2) EXISTING MOUNTING HOLES IN BOX TO MOUNT TO CROSS BAR. DRILL  $\phi$ .281 HOLES IN CROSSBAR.

